

Optional Accessories


- 937179T:** Footswitch
£45.30
- 09EAA084:** RS-232C signal cable 1 m (9 pin) for connecting DP-1VR to a PC
£174.00
- 965516:** GO / ±NO GO cable
£43.80



937179T

Consumable Spare

- 09EAA069:** Printer paper (1 roll)
£8.10



Key Functions

	Mode 0	Mode 1, 2
PRINTER ON/OFF		
CL	Only measurement data clear. Press before setting limit	
CE	Cancel the previous measurement data	
TOL. LIMIT	Press before entering or finish the upper/lower measurement mode. Cancel measurement mode.	
STAT	Do not operate	Making histogram to printout the calculation result via statistical analysis.
FEED	Printer paper is fed when this key is pressed	
DATA	Enter data via measuring devices	
PRINTER ON/OFF	Controls the printer's ON/OFF status	
POWER	Power ON/OFF	
	Mode 3	
PRINTER ON/OFF	Subgroup in measurement	Subgroup after measurement
CL	Re-entering from data No. 1	Only clear measurement data
CE	Cancel previous measurement data	Cancel previous subgroup
TOL. LIMIT	Exit the measurement	Go to next subgroup measurement
STAT	Finish the subgroup measurement printout the X-R calculation result.	Print out and calculate the control limit value from each subgroup to complete.
FEED	Printer paper is fed when this key is pressed	
DATA	Enter data via measuring devices	
PRINTER ON/OFF	Controls the printer's ON/OFF status	
POWER	Power ON/OFF	