


Quick Guide to Precision Measuring Instruments



Dial Gauges and Digital Indicators

Nomenclature



Dial Faces

0.01 mm



0.001 mm



Continuous dial: For direct reading
 Balanced dial: For reading the difference from a reference surface
 Reverse reading dial: For depth or bore gauge measurement
 One revolution dial: For error-free reading of small differences